

DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING





Michael O. Leavitt Governor

Kathleen Clarke

Executive Director Lowell P. Braxton

1594 West North Temple, Suite 1210 PO Box 145801 Salt Lake City, Utah 84114-5801 801-538-5340

801-359-3940 (Fax)

Complete: X Exploration:__ Partial:__ Inspection Date & Time: <u>9/29/99 2 to 4:30</u> Date of Last Inspection: 8/31/99

Ъ	ivision Director 801-538-7223 (IDD)				
N	Mine Name: <u>Horse Canyon Mine</u> County: <u>Carbo</u>	n Perr	nit Nun	ber: ACT/00)7/013 <i></i> %
	Permittee and/or Operator's Name: <u>UtahAmerican Energy</u> , Inc.				
	Business Address P.O. Box 986 Price, Utah 84501		D	0.05	
	Type of Mining Activity: Underground_X_ Surface Prep. Plant Other				
9	State Officials(s): <u>Susan White and Ken Wyatt</u>				
(Company Official(s): Paul Clark				
	ederal Official(s): None				
	Weather Conditions: Fair and cool				
		Described EO	Cooo	lad EO Pana	lod 71
	Existing Acreage: Permitted-74 Disturbed-63.6 F	kegraded- <u>59</u>	_ Seec	ieu- <u>39</u> build	160- <u>/ 1</u>
ı	ncreased/Decreased: Permitted Disturbed	_ Regraded-	Se	eaea Bo	naea-
· _					
(Status:Exploration/Active/Inactive/Tempo	orary Cessati	on/ Bo	ond Forfeitur	e
	Reclamation (40.9 Phase I/_Phase II/_Fir	•			Year)
	REVIEW OF PERMIT, PERFORMANCE STANDARDS				<u> </u>
<u>l</u>	nstructions				
1	. Substantiate the elements on this inspection by checking the ap	propriate perform	ance stan	idard.	tio not
	 For complete inspections provide narrative justification for a appropriate to the site, in which case check N/A. 	iny elements not t	ılıy insped	ctea uniess eieme	ent is not
	b. For <u>partial inspections</u> check only the elements evaluated.				
2	 Document any noncompliance situation by referencing the NOV 	issued at the appr	opriate pe	rformance stand	ard listed
-	below. Reference any narratives written in conjunction with this inspectio	n at the appropriate	norforma	noo etandard liete	d below
4	 Reference any narratives whiter in conjunction with this inspection. Provide a brief status report for all pending enforcement actions, 	n at the appropriate permit conditions.	Division (Orders, and amer	dments.
	The state of the s	EVALUATED		COMMENTS	NOVENE
1.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	<u>[X]</u>		[X]	
2.	SIGNS AND MARKERS	<u>[X]</u>	ĹŢ	ĺΧĴ	ГŢ
3.	TOPSOIL	<u>[X]</u>	Ш	- Ц	Ш
4.	HYDROLOGIC BALANCE: DIVERSIONS	[V]	r 1	ΓΥΊ	r 1
	SEDIMENT PONDS AND IMPOUNDMENTS		片	X	H
	OTHER SEDIMENT CONTROL MEASURES	iχi	H	ři	Ħ
d.	WATER MONITORING	ĪΧÌ	\Box	ΪΧΪ	
	EFFLUENT LIMITATIONS	X X X 	$\overline{\square}$	<u>[X]</u> [X]	ĹΪ
	EXPLOSIVES	ГŢ	ĺΧĴ	Ц	ГŢ
6. 7	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES		ĮΧĮ	Ļļ	Ӊ
8.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS NONCOAL WASTE	씑	片	 	ᆉ
9.	PROTECTION OF FISH, WILDLIFE AND	IVI	ш	1-1	ш.
٠.	RELATED ENVIRONMENTAL VALUES	[X]	[]	[]	[]
10.	SLIDES AND OTHER DAMAGE	[X] [X]	\Box		
11.	CONTEMPORANEOUS RECLAMATION		Ц	Ц	ГŢ
12.	BACKFILLING AND GRADING	įΧį	Ц	Ц	Ц
13. 14.	REVEGETATION SUBSIDENCE CONTROL	<u>K</u>	Η̈́		뷰
15.	CESSATION OF OPERATIONS	 	싂	 	片
16.	ROADS:	ш	11	1_1	
a.	CONSTRUCTION/MAINTENANCE/SURFACING	[]	[X]	[]	[]
b.	DRAINAGE CONTROLS		区		口
17.	OTHER TRANSPORTATION FACILITIES		<u>[X]</u>	ĹĪ	Ц
18.	SUPPORT FACILITIES/UTILITY INSTALLATIONS	ΪΧΪ	ΓŢ	Ц	Ц
19. 20.	AVS CHECK (4th Quarter-April, May, June) (date AIR QUALITY PERMIT	⇒ ∐	띥	片	<u> </u>
21.	BONDING & INSURANCE	ᅜ	쒀		<u> </u>
	- · · · - · · · = · · · · · · · · · · ·	17.71		15.71	ш

INSPECTION REPORT

(Continuation sheet)

Page 2 of 3

PERMIT NUMBER: ACT/007/013

DATE OF INSPECTION: 9/29/99

(Comments are Numbered to Correspond with Topics Listed Above)

1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE

The permit to conduct reclamation activities was issued December 21, 1998, to UtahAmerican Energy, Inc. Box 139, 10799 Pinetree Road, Pepper Pike, Ohio 44124. The permit expires May 6, 2001.

The UPDES permit was renewed 5/1/98 with no changes to monitoring or discharge. The discharge monitoring reports still state the names of the old Operators. Mr. Marshall has requested that the names on the DMRs be changed.

The Operator has applied for Phase II bond release. An on site inspection was conducted July 28, 1999. 63.6 acres are disturbed. 40.9 are eligible for Phase II Bond Release.

2. SIGNS AND MARKERS

Permit entry signs were visible upon entry into the permit area.

4. HYDROLOGIC BALANCE:

- a. DIVERSIONS The new diversion below the facility area had been installed. The diversion appeared more as a trench than as a ditch. Dave Darby, hydrologist, will be consulted concerning the design.
- b. SEDIMENT PONDS AND IMPOUNDMENTS The second quarter pond inspections were conducted and certified by R. Jay Marshall on May 13, 1999. Both ponds were dry. Pond 1 is to be removed when Phase II bond is released.
- d. WATER MONITORING Second quarter water monitoring samples were taken June 22, 1999. HC-1, RF-1, and RS-1 reported flows, B-1 (also known as HC-2) was dry. During this inspection Ken Wyatt, Division Hydrologist, recorded GPS locations and photographs for each water monitoring site. The GPS unit was unable to record data for HC-1 at this visit.
- e. EFFLUENT LIMITATIONS UPDES monitoring was reported as required, no discharge was reported.

21. BONDING AND INSURANCE

The insurance certificate is issued by Federal Insurance Co. and National Union. The producer of the certificate is Reschini Agency Inc. The policy is effective 6/1/99 to 6/1/00.

INSPECTION REPORT

(Continuation sheet)

Page <u>3</u> of <u>3</u>

PERMIT NUMBER: ACT/007/013

DATE OF INSPECTION: 9/29/99

A reclamation performance bond is held by Lincoln General Insurance Company in the amount of \$1,137,726.

On February 5, 1997 the Division authorized Phase I bond release for the reclaimed portion of the site.

Copy of this Report:

Mailed to: OSM, William W. Engels (IPA), Paul Clark, Jay Marshall (UAE)

Given to: DOGM

Inspector's Signature: Jusax M. White #35 Date: 9/30/99